

A permanent magnet synchronous motor includes a stator and a permanent magnet excited rotor, with the stator provided with a winding which has cyclically repeating winding factors  $|\xi_p|=0.945$ ,  $|\xi_{5p}|=0.140$ , and  $|\xi_{7p}|=0.060$ , and a skew angle  $\gamma=\frac{2\pi}{18p}$ , wherein p is the number of pole pairs.